


**PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
PART- 1**

(To be filled by the Head of School/ Institute)

1. Name of the School : **GREEN LAND SR. SEC PUBLIC SCHOOL**
2. Location : **G.T Road, Jalandhar Bye Pass, Ludhiana.**
3. Plot Area : **2.5 acres | 12100 sq. yards**
4. Plinth Area : **10000 sq.yards**
5. Number of Storey's : **Base/ Ground / first | Second | Third**
6. Year of Construction of Building: :**1992**
7. **If the building has been constructed under the supervision Of the qualified Engineer, the following details may be given::**
 - a) Name of the Engineer : **Mr. Verinder Kumar**
 - b) Address of Engineer : **B-IV , 1132 , Daresi Road , Ludhiana**
 - c) Set of Structural drawings used in the construction, if available : **ENCLOSED**
 - d) Name & address of Architect : **MRS. SHELJA GUPTA**
8. **Whether the building has been constructed for the purpose** :
 - a) School : **YES**
 - b) Residential Purpose and converted for use as a School : **NO**
9. **Materials used for roofs**
 - a) R.C.C. Slabs/R.B.C. Slabs : **YES**
 - b) R.S. Joist & Battons : **NO**
 - c) Wooden joists & Battons : **NO**
10. **Materials used for walls**
 - a) Mud Mortar : **NO**
 - b) Cement Mortar : **YES**
 - c) Lime Mortar : **NO**
11. **Flooring**
 - a) Conglomerate : **YES**
 - b) Terrazo : **NO**
 - c) Brick Paving. : **NO**
12. **A detailed drawing indicating dimensions of the rooms**
Along with size and location of doors and windows (Attached) : ENCLOSED


Signature with Stamp of the
GREEN LAND SR. SEC. PUBLIC SCHOOL
Head of the School/Institution.
Ludhiana

D/2023-24/61

PART-II

SP 16/5/2023.

(To be filled by the S.D.E.)

- a) I have visited the above mentioned school on dated 08/05/2023..... And have visually inspected it from all angles of safety and find it fit for normal use as School buildings.
- b) In case any addition/ alteration or expansion and modifications to this buildings is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be re-obtained after the completion from the undersigned.
- c) In case the building is affected by flood, or if there is settlement of walls/ foundations or sagging of roofs etc. immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d) This building can be safely occupied for normal use upto (indicate upto which it can be used) 31/03/2024.....

Amol
Sub Divisional Engineer,
Provincial Sub Division No. 8,
P.W.D. B&R, Br. LUDHIANA

Amol
Sub Divisional Engineer,